

SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <u>sales@acousticalsurfaces.com</u>
Visit our Website: <u>www.acousticalsurfaces.com</u>

## We Identify and S.T.O.P. Your Noise Problem



# T REPORT

Intertek Testing
Services NA, Inc.
16015 Shady Falls Road
Elmendorf, TX 78112
(V) 210-635-8100
(F) 210-635-8101
www.intertek-etlsemko.com

**ASTM E84-04** 

SURFACE BURNING CHARACTERISTICS OF BUILDING MATERIALS

Report No. 3081720-507

3497-010 Groove

September 8, 2005

Prepared for: Interface Fabrics Group 120 Gilboa Street East Douglas, MA 01516



SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <u>sales@acousticalsurfaces.com</u>
Visit our Website: <u>www.acousticalsurfaces.com</u>

## We Identify and S.T.O.P. Your Noise Problem

Report No. Report 3081720-507 Interface Fabrics Group Page 2 of 8 September 8, 2005

## **ABSTRACT**

Test Specimen: 3497-010 Groove

Test Standard: ASTM E84-04

Test Date: September 07, 2005

Test Sponsor: Interface Fabrics Group

Test Results:

FLAME SPREAD INDEX = 15 SMOKE DEVELOPED INDEX = 90

This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement, Intertek assumes no liability to any party other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to copy or distribute this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results on this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

September 8, 2005

Eric G. Hutchinson Project Manager

Reviewed and approved:

September 8, 2005

C. Anthony Peñaloza Project Manager



**SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS** 

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <u>sales@acousticalsurfaces.com</u>
Visit our Website: <u>www.acousticalsurfaces.com</u>

## We Identify and S.T.O.P. Your Noise Problem

Report No. Report 3081720-507 Interface Fabrics Group Page 3 of 8 September 8, 2005

#### INTRODUCTION

This report describes the results of the ASTM E84-04 Standard Test Method for SURFACE BURNING CHARACTERISTICS OF BUILDING MATERIALS, a method for determining the comparative surface burning behavior of building materials. This test is applicable to exposed surfaces, such as ceilings or walls, provided that the material or assembly of materials, by its own structural quality or the manner in which it is tested and intended for use, is capable of supporting itself in position or being supported during the test period.

The purpose of the method is to determine the relative burning behavior of the material by observing the flame spread along the specimen. Flame spread and smoke density developed are reported, however, there is not necessarily a relationship between these two measurements.

"The use of supporting materials on the underside of the test specimen may lower the flame spread index from that which might be obtained if the specimen could be tested without such support. This method may not be appropriate for obtaining comparative surface burning behavior of some cellular plastic materials. Testing of materials that melt, drip, or delaminate to such a degree that the continuity of the flame front is destroyed, results in low flame spread indices that do not relate directly to indices obtained by testing materials that remain in place."

This test method is also published under the following designations:

ANSI 2.5 NFPA 255 UBC 8-1 (42-1) UL 723

This standard should be used to measure and describe the properties of materials, products, or assemblies in response to heat and flame under controlled laboratory conditions and should not be used to describe or appraise the fire hazard or fire risk of materials, products, or assemblies under actual fire conditions. However, results of this test may be used as elements of a fire risk assessment which takes into account all of the factors which are pertinent to an assessment of the fire hazard of a particular end use.



#### SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <u>sales@acousticalsurfaces.com</u>
Visit our Website: <u>www.acousticalsurfaces.com</u>

## We Identify and S.T.O.P. Your Noise Problem

Report No. Report 3081720-507 Interface Fabrics Group Page 4 of 8 September 8, 2005

## **II PURPOSE**

The ASTM E84-04 (25 foot tunnel) test method is intended to compare the surface flame spread and smoke developed measurements to those obtained from tests of mineral fiber cement board and select grade red oak flooring. The test specimen surface (18 inches wide and 24 feet long) is exposed to a flaming fire exposure during the 10 minute test duration, while flame spread over its surface and density of the resulting smoke are measured and recorded. Test results are presented as the computed comparisons to the standard calibration materials.

The furnace is considered under calibration when a 10 minute test of red oak decking will pass flame out the end of the tunnel in five minutes, 30 seconds, plus or minus 15 seconds. Mineral fiber cement board forms the zero point for both flame spread and smoke developed indexes, while the red oak flooring smoke developed index is set as 100.

#### III DESCRIPTION OF TEST SPECIMEN

Specimen Identification: 3497-010 Groove

Date Received: 8/3/2005 Date Prepared: 8/3/2005

Conditioning (7 3°F & 50% R.H.): 35 days

Specimen Width (in): 24 Specimen Length (ft): 24

Specimen Thickness: 0.0200-in.

Material Weight: N/A oz./sq. yd

Total Specimen Weight: 2.50-lbs.

Adhesive or coating application rate: N/A

#### Mounting Method:

The specimen was supported on 1/4 in steel rods and 2 inch galvanized hexagonal wire mesh.

## Specimen Description:

The Test specimen was described by the client as the "100% Polyester Panel Fabric." The specimen consisted of (2) 12-ft. long x 24-in. wide x 0.0200-in, thick, 100% Polyester Panel Fabric. The specimen was dark green in color. The specimen was identified by the client as "3497-010 Groove".



## SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <a href="mailto:sales@acousticalsurfaces.com">sales@acousticalsurfaces.com</a>
Visit our Website: <a href="mailto:www.acousticalsurfaces.com">www.acousticalsurfaces.com</a>

## We Identify and S.T.O.P. Your Noise Problem

Report No. 3081720-507 Interface Fabrics Group Page 5 of 8 September 8, 2005

#### IV TEST PROCEDURE

The tests were conducted in accordance with the procedures outlined in the American Society for Testing and Materials ASTM E84-04. The self-supporting specimens were placed directly on the tunnel ledges. After the tests, the samples were removed from the tunnel, examined and disposed of.

The test was conducted on 9/7/2005, and not witnessed by any third parties.

## V TEST RESULTS

The test results, computed on the basis of observed flame front advance and electronic smoke density measurements are presented in the following table. In recognition of possible variations and limitations of the test method, the results are computed to the nearest number divisible by five, as outlined in the test method for smoke developed index results greater than 200 the calculated value is rounded to the nearest 50 points.

While no longer a part of this standard test method, the Fuel Contributed Value has been computed, and may be found on the computer printout sheet in the Appendix.

	Flame Spread	Smoke
Test Specimen	Index	Developed Index
Mineral Fiber Cement Board	0	0
Red Oak Flooring	85	85
3497-010 Groove	15	90

The data sheets are included in the Appendix. These sheets are actual print-outs of the computerized data system which monitors the ASTM E84-04 apparatus, and contain all calibration and specimen data needed to calculate the test results.

#### VI OBSERVATIONS

During the test, the specimen was observed to behave in the following manner: The specimen began to melt at 0:04 (min:sec.). Flaming drops began to fall from the fabric at 0:06 (min:sec). The fabric ignited at 0:15 (min:sec). The melted polyester continued to burn on the floor of the apparatus at 0:20 (min:sec.). The test continued for the 10:00 duration.

After the test specimen was observed to be damaged as follows:

The fabric was consumed from 0-ft. - 12-ft. Light discoloration was observed to the fabric from 12-ft. - 24-ft.



SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <u>sales@acousticalsurfaces.com</u>
Visit our Website: <u>www.acousticalsurfaces.com</u>

## We Identify and S.T.O.P. Your Noise Problem

Report No. 3081720-507 Interface Fabrics Group Page 6 of 8 September 8, 2005

## **APPENDIX**

ASTM E84-04
Data Sheets



SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <a href="mailto:sales@acousticalsurfaces.com">sales@acousticalsurfaces.com</a>
Visit our Website: <a href="mailto:www.acousticalsurfaces.com">www.acousticalsurfaces.com</a>

## We Identify and S.T.O.P. Your Noise Problem

## **ASTM E84 DATA SHEETS**

Client: INTERFACE FABRICS

Date: 9/7/05 Time: 02:01 PM

Test Number 3

Project Number: 3081720-507

Operator EH/TA

Specimen ID: "3497-010 GROOVE,100% POLYESTER PANEL FABRIC". THE

SPECIMEN WAS SUPPORTED BY RODS & WIRE. THE SAMPLE WAS

NOT UNDER INTERTEK Q.A.

## **TEST DATA**

FLAMESPREAD INDEX 15
SMOKE DEVELOPED INDEX 90

## SPECIMEN DATA ...

Time to Ignition (sec): 15
Time to Max FS (sec): 29
Maximum FS (feet): 2.6

Time to 980 °F (sec): Never Reached

Max Temperature (°F): 518

Time to Max Temperature (sec): 585

Total Fuel Burned (cubic feet): 50.74

FS\*Time Area (ft\*Min): 25.8 Smoke Area (%A\*min): 75.8 Fuel Area (°F\*min): 4395.5 Fuel Contributed Value: 0

Unrounded FSI: 13.3

## CALIBRATION DATA ...

Time to Ignition of Last Red Oak (sec): 39

Red Oak Smoke Area (%A\*min): 85.00

Red Oak Fuel Area (°F\*min): 9036

Glass Fiber Board Fuel Area (°F\*min): 5401




SOUNDPROOFING, ACOUSTICS, NOISE & VIBRATION CONTROL SPECIALISTS

123 Columbia Court North • Suite 201 • Chaska, MN 55318 (952) 448-5300 • Fax (952) 448-2613 • (800) 448-0121

Email: <a href="mailto:sales@acousticalsurfaces.com">sales@acousticalsurfaces.com</a>
Visit our Website: <a href="mailto:www.acousticalsurfaces.com">www.acousticalsurfaces.com</a>

## We Identify and S.T.O.P. Your Noise Problem



Soundproofing Products • Sonex™ Ceiling & Wall Panels • Sound Control Curtains • Equipment Enclosures • Acoustical Baffles & Banners • Solid Wood & Veneer Acoustical Ceiling & Wall Systems
 • Professional Audio Acoustics • Vibration & Damping Control • Fire Retardant Acoustics • Hearing Protection • Moisture & Impact Resistant Products • Floor Impact Noise Reduction
 • Sound Absorbers • Noise Barriers • Fabric Wrapped Wall Panels • Acoustical Foam (Egg Crate) • Acoustical Sealants & Adhesives • Outdoor Noise Control • Assistive Listening Devices

<sup>•</sup> OSHA, FDA, ADA Compliance • On-Site Acoustical Analysis • Acoustical Design & Consulting • Large Inventory • Fast Shipment • No Project too Large or Small • Major Credit Cards Accepted